


Another design or thought  
Could ~~the~~ possibly weld while on  
Machine.



Same as on bottom.

One could split 3 point sleeve  
Bushing be sure it is  $\frac{3}{4}$  circum-  
inside